Dart Aerospace Ltd. Wednesday, 5/3/2006 11:50:04 AM User: Linda Lacelle **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : SUPPORT GUSSET (350) BASKET **Job Number** : 26922 : 10496 **Estimate Number** :NIA P.O. Number **Part Number** : D2325 S.O. No. : NA This Issue : 5/3/2006 : D2325 REV B **Drawing Number** : NC Prsht Rev. : N/A **Project Number** : N/A : PURCHASED PARTS First Issue Type : B **Drawing Revision** : NIA : 26922 **Previous Run** Material **Due Date** : 5/10/2006 Qty: 20 Um: Each Written By COMMENT BELOW Checked & Approved By Comment Reformat; Rev B Est. E06.05.03 Water jet EC **Additional Product** Job Number: Seq. #: **Machine Or Operation: Description:** 1.0 M304S16GA 304/316 .063 Sheet Comment: Qty.: Total: 9.7650 sf(s) 0.4883 sf(s)/Unit Batch: M7106 304/316 SS .063 Sheet WATER JET 2.0 FLOW WATER JET Comment: FLOW WATER JET 1-Cut as per Dwg D2325 Dwg Rev: 13 Prog Rev: 3 2-Deburr if necessary 3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE

SECOND CHECK

SMALL & MEDIUM FAB RESOURCE 1

4.0

5.0

QC8

Comment: SECOND CHECK

SMALL FAB 1

Comment: SMALL & MEDIUM FAB RESOURCE.1

Deburr if necessary

Date: Wednesday, 5/3/2006 11:50:05 AM User: Linda Lacelle **Process Sheet** Drawing Name: SUPPORT GUSSET (350) BASKET Customer: CU-DAR001 Dart Helicopters Services Job Number: 26922 Part Number: D2325 Job Number: Seq. #: **Machine Or Operation:** Description: INSPECT WORK TO CURRENT STEP 6.0 QC5 Dø Comment: INSPECT WORK TO CURRENT STEP 7.0 PACKAGING 1 PACKAGING RESOURCE **Comment: PACKAGIN** Identify and Stock Location: <u>い</u>ら 8.0 DOCUMENT CONTROL DO6/05/04 **Comment: DOCUMENT CONTROL** Inspection Level 21 Job Completion

User:

Wednesday, 5/3/2006 8:25:27 AM

Linda Lacelle

Process Sheet Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : SUPPORT GUSSET (350) BASKET Job Number : 26922 : 10496 **Estimate Number** P.O. Number Part Number : D2325 This Issue : 5/3/2006 S.O. No. : : D2325 REV B **Drawing Number** : NC Prsht Rev. : N/A **Project Number** : B First Issue : // : PURCHASED PARTS Type **Drawing Revision** : 26741 **Previous Run** Material **Due Date** : 5/10/2006 Qty: 10 Um: Each Written By Checked & Approved By Comment : Est. D 02.12.06 Reformat; Rev B KJ/RF **Additional Product** Job Number: Seq. #: **Machine Or Operation:** Description: PURCHASING 1.0 PG Comment: PURCHASING Issue P/O: Email or ship DXF file to venderMake as per Dwg D2325 Material: 304 SS .063" Thick Material release note required 2.0 D2325F Support Gusset (350 Bask M3045166A 0.465 sf Comment: Qtv.: 1.0000 Each(s)/Unit Total: 3.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Récieive & Inspect for Transit Damage Ensure Material Release Note is attached 4.0 DIMENSIONAL CHECK Comment: DIMENSIONAL CHECK SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Deburr if necess

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES	WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector					
		WORK ORDER NOW CONTORNAL										

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Approval	Approval				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector				

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date: _	
NOTE: Date & initial all entries				QA:	N/C C	losed:	Date:	• 1

Date: User:

Wednesday, 5/3/2006 8:25:27 AM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SUPPORT GUSSET (350) BASKET

Job Number: 26922

Part Number: D2325

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGIN Identify and Stock

Location:

DOCUMENT CONTROL



7.0

DC



Inspection Level 21



Job Completion





Dart Aerospace Ltd

W/O:		WORK ORDER CHAN	WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector					

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval Design Mgr	Anneval			
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C		Approval QC Inspector			
							1				
-	5	, *						_			
		· .									
·											
				`							
			i	. •							

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries	Control of the second		•	QA: N	/C CI	osed:	Date:





DART AEROSPACE LTD	Work Order: 26922
Description:	Part Number: D2325
Inspection Dwg: Rev:	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
00.257	+/-0-010	0.257	J		vein	
1,000	+1-0.010	1.01	1		vern	
0.500	4-0.010	0.500	.√		yern	
4.382	1-0.010	4.376	1		Vern	
10.915	1- 000	10.915			TAPE	
1.569	+010	1.569			vern	
4.36	1=7010	4-36			NEER	not important.
		,				
		1				
						·
	-					·
		-				
		:				
						- منز ع
			ď			
L						

Measured by:	Audited by:	Prototype Approval:	NIA
Date: 06 の	03 Date: 06 05.03	Date:	NIA

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	



